Search Notes



A	ppl	icati	on/C	Contr	ol No.	

10/771,083 Examiner

Toan M. Le

Applicant(s)/Patent under Reexamination

HOFMEISTER ET AL. Art Unit

2863

SEARCHED						
Class	Subclass	Date	Examiner			
702	120	5/24/2005	TL			
372	38.1	5/12/2005	TL			
372	50	5/12/2005	TL			
257	688	5/20/2005	TL			
385	92	5/20/2005	TL			
385	93	5/20/2005	TL			
372	38.02	5/23/2005	TL			
Above	Updated	12/22/2005	TL			
Above	Updated	7/21/2006	TL			
398	135	7/21/2006	TL			
Above	Updated	3/3/2007	TL			
372	26,29.021	3/3/2007	TL			
398	182,186	3/3/2007	TL			

INTERFERENCE SEARCHED						
Class	Subclass	Date	Examiner			
-						
	-		<u> </u>			

SEARCH NOT (INCLUDING SEARCH)
	DATE	EXMR
Electrostatic Discharge Damage, Photodiode, Laser	5/12/2005	TL
Laser Diode, Switch, Transceiver, Pins	5/12/2005	TL
Transceiver Module, Laser Diode	5/12/2005	TL
VCSEL, Laser Drive, Laser Diode, Transceiver	5/23/2005	TL
702/120; 372/38.1,38.02; 257/688; 398/135 (Laser Diode)	7/21/2006	TL ·
702/120; 372/26,29.021,38.1,38.02,50; 257/688; 385/92,93; 398/135,182,186 (VCSEL Operating reference Characteristics)	3/3/2007	TL
East- See Search History Printout	3/3/2007	TL